

# Manhole Inspection Summary

Manhole # S15EE1003MH

Printed On: 3/12/2009

Page 1 of 3

**Inspection** ☒ **Is Incomplete** Rating: **2) Good**

Record Plat: **15EE1** Node: **003** Status: **Found**

Insp Date: **10/20/08 1:40 PM**

Incomplete Comments

**Cannot Access - Terminal Manhole Filled With Concrete to Rim**

Crew: **ADS1**  
Inspector: **ADS1**  
Firm: **ADS**

**Location** Address: **ALLEY BETWEEN COTTAGE &** Cross Street: **PALL MALL**

**Manhole** Type: **Terminal** Location: **Alley** Ground Conditions: **Dry**  
☐ Prev. Rehab Weather: **Dry** Subject To Ponding: **None**

Comments **MANHOLE IS ABANDONED IT WAS FILLED WITH CONCRETE TOOK PICTURES OF AREA AND TOPVIEW**

**Cover** Shape: **Circular** Diameter: **25.** (in.) Length: (in.) Dist A/B Grade: **0** (in.)  
**75**

Type: **Sanitary** Condition: **Sound** Cover Material: **Cast Iron**

Properties: ☐ Bolted ☒ Vented ☐ Water Tight ☐ Water Tight Insert

**Frame** Offset: **0** (in.) Condition: ☒ Sound ☐ Cracked ☐ Leaks

**Chimney / Frame Adjustment** ☐ Exists Material: ☐ Parged Height: (in.)

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

**Corbel** Material: **Brick** ☐ Parged Type: **Concentric/Eccentric**

Condition: ☒ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☒ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

**Barrel** Material: **Brick** ☐ Parged

Shape: **Circular** Diameter: **30** (in.) Length: (in.)

Condition: ☒ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☒ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

**Bench** ☐ Exists Material: ☐ Parged

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

**Channel** Material: **Unknown** ☐ Parged

Channel Exposure: **Fully Open** Junc Dist: **0** nearest .5 ft. Azimuth:

Condition: ☒ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

**Steps** Count: **0** Missing: **0** ☐ Corroded

**Surcharge** ☐ Evidence Of Surcharge Depth: (ft.) ☐ Active Surcharge Present

# Manhole Inspection Summary

Manhole # S15EE1003MH

Printed On: 3/12/2009

Page 2 of 3

Location View



Top View



Manhole Inspection Summary

Manhole # S15EE1003MH

Printed On: 3/12/2009

Page 3 of 3

8 in. Circular Gravity Sewer

12 O'Clock Outflow

Pipe Height: (in.) Direct

Pipe Material: Unknown ☐ Pipe Lined

Invert Depth: 2.00 (ft.) Flow Characteristics: None

Deposits: ☒ None ☐ Mud ☐ Sludge ☐ Debris ☐ Grease

Silt Depth: (in.) Deposits Extent:

Infiltration: None Pipe Seal Cond: Unknown

Drop: None

Connects To: Manhole

☐ Possible Illicit Connection